

Lakeview Church Work Projects

Where	What	Materials
Youth/office building – stair landing just inside the main door.	Rubber stair edging on top step coming from the basement is split.	No materials have been purchased. You need to find matching material.
East side of main building.	Caulk has been chipped out of fascia, new caulk needs to be applied as needed.	Please purchase caulk as needed.
Main building basement.	Some chairs are broken or missing rubber feet. Replace missing feet. Sort out broken chairs for repair or disposal.	Contact Paul Trantham for materials.
North center basement room of main building.	Light fixture cover is held on with duct tape. Closure clip is missing.	Purchase clip from hardware store.
Narthex ceiling	Repair ceiling where water leak caused damage.	See John Korpi for materials.
Youth building – southwest corner	Dirt has washed away and exposed drain tile. Place edging at end of planting bed.	Edging is in the garage.
Washrooms in both buildings	Toilet flapper valves are deteriorating. Check all toilet tanks and replace valves as necessary.	Contact Carlton Smith for information on materials.
Youth building gutters	Put leaf guards over gutters	Gutter guards are in the garage.
Bushes along north side of east parking lot	Trim as needed	Please use your own tools. Debris should be bundled with twine into bundles no more than 36" long and placed on the north side of the garage for the time being.